

Capacitor Replacement Kit  
This is not a repair kit  
Suzo-Happ No. 70-26107-00  
3Y Power Technology  
CP9826

Installation Instructions

1 – 47uF @ 50V	2 – 2200uF @ 35V
1 – 4.7uF @ 50V	1 – 1000uF @ 35V
1 – 470uF @ 16V	1 – 3300uF @ 16V
1 – 100uF @ 25V	2 – 220uF @ 35V
2 – 10uF @ 50V	1 – 33uF @ 35V

Replace all the parts even though many of the original parts seem to be working fine because age, humidity, and temperature cause the value of the electrolytic capacitors to change. Installing all of the parts will assure many more years of trouble free service.

All the capacitors are polarized and can only be inserted in one direction. Watch the markings for polarity on each capacitor.

C27 – 47uF @ 50V	C17 – 1000uF @ 35V
C2 – 4.7uF @ 50V	C21 – 2200uF @ 35V
C7 – 470uF @ 16V	C15 – 3300uF @ 16V
C18 – 220uF @ 25V	C28 – 220uF @ 35V
C16 – 2200uF @ 35V	C29 – 220uF @ 35V
C37 – 10uF @ 50V	C36 – 33uF @ 35V
C35 – 10uF @ 50V	