


ROM REPLACEMENT

BL-700


APPENDIX 1. MASTER ROM – REPLACEMENT

(1) To replace the Master Rom is quite easy. All you will need is a screwdriver.

Remove the plastic cover on the bottom of the bill acceptor with the screwdriver.






Bottom of bill acceptor



Remove plastic cover

Remove the current EPROM from the validator.



Please note that the pins should not be curved or bent.